

Avigilon H4 Thermal Cameras

Firmware Release Notes

Version 3.22.0.36 – Released Feb 2, 2018

- Corrects an issue with FW version 3.18.0.34 where the camera may reboot randomly. All users should update to this version.

Version 3.22.0.34 – Released Jan 16, 2018

- Resolves a privilege escalation issue for operator and user accounts where HTTP or CGI commands are being executed as an administrator account. We highly recommend all users to update to this release.

Version 3.22.0.32 – Released December 11, 2017

- Initial firmware release for the following H4 Thermal cameras:
 - 320S-H4A-THC-BO50
 - 320S-H4A-THC-BO24
 - 320S-H4A-THC-BO12