

Avigilon HD PTZ Firmware Release Notes



Version 2.6.0.150 – Released November 17, 2016

New Features

- Upgraded OpenSSL to v1.0.2h improve security between client and server.
- Added a feature where the maximum move speed of the PTZ can be configured.

Issues Fixed

- Fixed an issue where triggering a digital output would prevent the user from applying changes to Digital Inputs and Outputs settings in the WebUI.
- Fixed an issue where the NTP server would not revert to default settings when Restore Defaults is executed in the WebUI.
- Fixed an issue where the time zone and day light savings settings would not revert to default settings when Restore Defaults is executed in the WebUI.
- Fixed an issue where Kanji characters in the camera name would corrupt the time zone settings.
- Fixed an issue where configuring the camera to use a static IP address in the WebUI then back to DHCP would cause the camera to report the IP address in the wrong part of the ONVIF message.

Version 2.6.0.144 – Released October 1, 2016

Issues Fixed

- Fixed an issue so that back light compensation via ONVIF allows Mode and Level fields to be configured independent of one another.

Version 2.6.0.134 – Released April 6, 2016

Issues Fixed

- Fixed an issue where the camera would randomly reboot

Version 2.6.0.120 – Released March 11, 2016

Issues Fixed

- Fixed a time synchronisation issue that appeared in some cameras

Version 2.6.0.108 – Released January 14, 2016

Issues Fixed

- Fixed an issue where zooming with a joystick would cause the ACC Server software to crash
- Fixed an issue where the camera WebUI misrepresented the saturations settings

Avigilon HD PTZ

Firmware Release Notes



- Fixed an issue where the status bar was missing from some WebUI pages
- Fixed an issue where the camera would reboot every 45 days
- Fixed an issue where configuring the camera to a static IP and back to DHCP in the WebUI would cause the camera to report the IP address in the wrong part of the ONVIF message.
- Camera now correctly switches between color and monochrome mode based on the appropriate ambient light levels

Version 2.6.0.104 – Released October 22, 2015

New Features

- Upgraded OpenSSL version to improve security between client and server

Issues Fixed

- Corrected the behaviour where the WebUI would appear to have started the upgrade but the upgrade was not actually triggered
- Fixed an issue with the WebUI where the icons under motion detection would not display properly
- Fixed a security issue where the 802.1x passwords were being returned in plaintext
- Fixed an issue where changing some camera settings would error out the camera
- Corrected an issue where a space character in the 802.1x description prevents it from being used
- Camera now reports correct secondary stream resolutions in MJPEG mode
- Fixed an issue where creating or saving a 802.1x configuration with “ character would prompt multiple login instances in the WebUI
- Corrected an issue where the pan limits could not be set properly
- Corrected the image resize behaviour where selecting the PTZ icon on the ACC Client toolbar would cause image artifacts.

Version 2.6.0.92 – Released May 25, 2015

Issues Fixed

- Corrected the ONVIF response as MotionActive for both Pull Message and Get Event Properties responses

Version 2.6.0.88 – Released April 21, 2015

Issues Fixed

- Corrected an issue where the camera would not go to the correct preset position

Avigilon HD PTZ Firmware Release Notes



Version 2.6.0.86 – Released March 13, 2015

New Features

- Added an information display to report the current digital input status
- Added support for UTF-8 and UTF-32 characters in the camera name and location fields

Issues Fixed

- Corrected an issue where the camera would not zoom to a selected area
- Corrected the port range used for RTP / RTCP connections from 51000-63000 to 51000-55000
- Fixed a web server generic cookie injection and web server generic XSS vulnerability
- Corrected an audio issue where the audio stream would be garbled when audio stream is connected to two ACC servers simultaneously
- Corrected an issue where a Katakana name entered into the 802.1x UI may cause the camera to reboot

Version 2.6.0.68 – Released January 5, 2015

New Features

- Added an adjustable MTU setting

Issues Fixed

- Corrected issue where unwanted errors were being saved to the camera logs when a Web UI connection was opened

Version 2.6.0.54 – Released November 3, 2014

Issues Fixed

- Motion is no longer detected underneath a privacy mask
- Corrected issue where changing from 60Hz to 50Hz flicker control prevented additional privacy zones from being created
- Values can now be entered into the pan tilt limit in the Web UI configuration page
- Corrected issue where a PTZ would be forced to move to the first privacy zone when the privacy zone configuration page is loaded in Web UI
- Corrected an issue on Internet Explorer where the 'Apply' button would be clickable when no changes were made on the Web UI tour configuration section

Avigilon HD PTZ Firmware Release Notes



Version 2.6.0.46 – Released September 8, 2014

New Features

- Added support for GB compliant mode of operation

Version 2.6.0.36 – Released July 4, 2014

Issues Fixed

- NTP configuration dialog controls fixed to properly reflect configured settings
- Switching 802.1x configuration when using certificate based authentication is now working
- Certain tour presents may become stuck or skip over certain positions

Version 2.6.0.32 – Released May 16, 2014

New Features

- 802.1x authentication support using PEAP and EAP-TLS

Issues Fixed

- When PoE is used incorrectly to power the camera, the camera will only stream but not reboot or move

Version 2.6.0.20 – Released March 26, 2014

New Features

- Increased maximum number of privacy masks to 64

Version 2.6.0.14 – Released December 24, 2013

New Features

- Smoother PTZ movement when fully zoomed in

Issues Fixed

- Improved responsiveness of WebUI interface
- Apply button on PTZ limits page on WebUI is enabled after a setting is changed

Version 2.4.4.36 – Released July 30, 2013

New Features

- Ability to stream from camera to an FFmpeg player
- Full resolution still image HTTP URI available in web interface when primary stream compression is MJPEG

Avigilon HD PTZ Firmware Release Notes



- ONVIF Profile S conformant

Issues Fixed

- ONVIF support for move with a speed of zero command
- Improved backlight compensation range
- WebUI Apply button is only enabled if something is changed
- WebUI System page is refreshed after an upgrade/reboot/restart
- DHCP gateway displayed correctly in web interface

Version 2.4.4.20 – Released December 14, 2012

New Features

- Smoother zoom movements with improved focus tracking reducing auto-focus time in many conditions
- Motion detection is enabled with reduced sensitivity during auto-focusing after moving to a preset
- PTZ limits web user interface page improved
- ONVIF communication enhancements
- Multiple zoom speeds supported
- Extended browser support for web user interface

Issues Fixed

- Minimum focusing distance of camera increased to avoid potentially focusing on the bubble
- Potential issue running an empty tour is resolved
- Focus button functionality issue resolved
- Multiple issues related to mechanical limits are fixed
- Status LED behavior updated
- GetPtzStatus in ONVIF returns absolute coordinates in the correct [-1, 1] range for Pan/Tilt
- Minor issues with privacy zones are fixed
- Rare potential camera time-sync issue is resolved
- Genetec connection issue is resolved
- Presets per tour are limited to 100
- WebUI is now compatible with many older browsers
- Various web user interface issues resolved

Avigilon HD PTZ Firmware Release Notes



Version 2.4.4.0 – Released August 31, 2012

New Features

- Initial release of firmware for the following HD PTZ cameras
 - 1.0W-H3PTZ-DP20
 - 2.0W-H3PTZ-DP20