

Avigilon HD H.264 Pro Firmware Release Notes

Version 3.10.2.8 – Released November 29, 2016

Issues fixed:

- Fixed an issue where the MIB files would sometimes generate an error upon upload.
- Fixed an issue where the bandwidth limits were not enforced during Idle Scene Mode.

Version 3.10.0.162 – Released November 10, 2016

New Features:

- Added support for RTSP streaming of secondary stream

Issues fixed:

- Updated the copyright notice to 2016 on the SNMP MIB files
- Corrected an issue where the wrong object type was returned for SNMP Temperature ID
- Reduced latency of analytic bounding box behind a moving classified object
- Allowing spaces to be used in naming 802.1X configuration
- Updated signed FW CRL from 2016 to 2116

Version 3.10.0.138 – Released Sept 6, 2016

Issues fixed:

- Fixed an issue where cameras may experience a gradual reduction in encoding framerate

Version 3.10.0.124 – Released June 27, 2016

New Features:

- Added support for on screen overlays for the primary stream

Issues fixed:

- Fixed an issue where the camera would not use the Teach By Example markers
- Fixed an issue where the camera would drop frames when exiting Idle Scene Mode for high bandwidth scenes
- Fixed an issue where performing Restore to Factory Defaults would not restore the SNMP settings to default values
- Fixed an issue where ARP ping IP address settings conflicted with Link Layer Discovery Protocol result in a fixed IP conflict
- Default key frame interval restored to 30
- Default exposure under 50Hz flicker control restored to 33.3ms

Avigilon HD H.264 Pro Firmware Release Notes

Version 3.10.0.106 – Released April 25, 2016

Issues fixed:

- Fixed an issue where the camera would randomly reboot

Version 3.10.0.92 – Released March 3, 2016

New Features:

- Added support for Idle Scene Mode.
- Firmware packages are signed to verify authenticity.
- Upgraded to OpenSSL version 1.0.2d to improve security when streaming data between the ACC client and server.
- Exposure offset can be manually configured.
- The threshold for switching day/night mode is now controlled by a slider in the WebUI.
- SNMP is now configurable via WebUI to version 2c or 3. When using SNMP v3, the username and password can be configured in the WebUI.

Issues fixed:

- Fixed an issue where the camera would reboot every 45 days.
- Fixed an issue where the firmware upgrade would not start when the Upgrade button is clicked.
- Resolved an issue where AutoFocus would cause the camera to reboot.
- Fixed an issue where the motion detection area would exceed the image window.
- Fixed an issue where changing the motion detection sensitivity would cut off part of the detection area.
- Resolved issues with the compression formats that caused the Max Bitrate to drop to 0.
- Improved motion detection under low light conditions.
- Fixed an issue where changing the camera IP in the WebUI to static then back to DHCP cause the camera to report the IP address in the wrong part of the ONVIF message.
- Improved WebUI status bar so that it displays on all pages.
- Fixed an issue where the saturation parameter is reported incorrectly in ACC and WebUI.

Version 3.8.0.8 – Released September 29, 2015

New Features:

- Fixed an issue where the cameras randomly reboot
- Improved focus feature for EFMount cameras in the WebUI
- Added a feature where the effective max bitrate is independent of image framerate
- Added a feature where the maximum aperture can be configured
- Rationalized the default key frame interval

Avigilon HD H.264 Pro Firmware Release Notes

- Increased the maximum gain to 60dB

Issues fixed:

- Fixed an issue where Privacy Zone boxes were altered by manual change of exposure
- Fixed an issue where the WebUI preview would malfunction if ACC was disconnected
- Fixed an issue where outlines of objects were visible under the Privacy Zone box
- Corrected a problem where setting Privacy Zones on the WebUI would not apply
- Improved performance at low frame rates
- Fixed issues with dropping frames
- Fixed an issue where the privacy zones near the bottom of the screen would not apply properly

Version 3.4.2.6 – Released May 8, 2015

New Features:

- Added Self-Learning Video Analytics features to 8L-H4PRO-B, 12L-H4PRO-B and 16L-H4PRO-B
- SD Card recording defaults to record only when server connection is interrupted
- Added support for UTF-8 and UTF-32 characters in the camera name and location fields

Issues fixed:

- Corrected an issue where a camera may overexpose when in manual exposure
- Fixed a web server generic cookie injection and web server generic XSS vulnerability
- Corrected the port range used for RTP / RTCP connections from 51000-63000 to 51000-55000
- Corrected an issue where the “Apply” and “Restore Buttons” in the Web UI do not appear when using Internet Explorer 11
- Corrected an issue where a Katakana name entered into the 802.1x UI may cause the camera to reboot

Version 3.0.0.40 – Released Dec 15, 2014

New Features:

- Added option to retain usernames and password on firmware revert

Issues fixed:

- Corrected an issue where a camera may overexpose when aimed at a sunrise
- Fixed issue where a user with user level permission may lock up the camera streaming by attempting a firmware upgrade

Avigilon HD H.264 Pro Firmware Release Notes

- Fixed issue where a Katakana Unicode user name would not appear in the user administration page

Version 3.0.0.36 – Released October 31, 2014

New Features:

- Number of privacy zones increased to 64
- Added ability to take a JPEG snapshot to an SD card when in MJPEG compression mode
- Added 802.1x port based authentication feature

Issues fixed:

- Corrected tilt direction reversal and preset issue when used with Ulisse Maxi NetCam
- Corrected issue where a camera would be severely overexposed when paired with specific lenses such as the LEF2018SI
- Fixed issue where audio input would be garbled if the camera was connected to more than one ACC server
- Fixed issue with real-time clock where the month may not be correct for SD card recordings
- Fixed issue where an SD card may become unusable after removal from the camera
- Fixed issue where 1/7s (133ms) exposure was unavailable under 60Hz flicker control
- Fixed issue where swapping lenses while the camera is powered on may result in a failure of the camera to identify the correct lens attached.

Version 3.0.0.26 – Released June 18, 2014

New Features:

- In automatic exposure, increased gain range from 6dB to 54dB. In manual exposure, the gain may be set from 0dB to 54dB.
- Improved onboard storage download speeds

Issues fixed:

- Changing from MJPEG to H.264 will no longer reset the keyframe interval to 2.
- The orange power LED will now be on as soon as the camera powers on
- Encoding restart is faster after a frame rate change
- Privacy zone setting screen will refresh properly on Chrome browser
- Some SD cards failed to format properly
- PTZ controls in Web UI are now working properly

Avigilon HD H.264 Pro Firmware Release Notes

Version 3.0.0.12 – Released Apr 10, 2014

- Initial release of firmware for the following HD H.264 Pro cameras:
 - 16L-H4PRO-B
 - 12L-H4PRO-B
 - 8L-H4PRO-B