

## Version 3.24.2.76 – Released May 29, 2018

### *New Features*

- Added support for Unusual Motion Detection
- Added support for IPv6
- Added support for on screen overlay on secondary streams
- Allows use of external NTP server even when camera is connected to an ACC server

### *Issues Fixed*

- Fixed an issue where camera framerate was limited when using idle scene mode with large secondary streams
- Fixed an issue where camera streams may de-synchronize due to use of idle scene mode
- Fixed an issue where 802.1x authentication fails if a CA certificate is removed and deselecting authenticate server option

## Version 3.16.0.234 – Released March 19, 2018

### *Issues Fixed*

- Corrected an issue where cameras are reporting “pipeline restart” in the camera logs which may result in a short recording gap
- Corrected an issue where the image appears to be flickering or oscillating exposure

## Version 3.16.0.222 – Released November 20, 2017

- Internal manufacturing release

## Version 3.16.0.208 – Released Sept 19, 2017

### *New Features*

- Enables control over motion compensated temporal noise filter strength
- Improved image exposure and quality when IR is enabled and WDR is enabled

### *Issues Fixed*

- Corrected an issue where highlight areas details were blown out in WDR mode
- Corrected an issue where brightness adjustments in WDR mode were leading to image degradation

## Version 3.16.0.194 – Released August 18, 2017

- Corrects an issue where HDSM SmartCodec was not functioning even if enabled

## Version 3.16.0.186 – Released July 21, 2017

- Internal manufacturing release

## **Version 3.16.0.174 – Released July 11, 2017**

- Fixes critical vulnerability CVE-2017-9765. While the risk for Avigilon products installed behind a firewall or isolated network is limited, we highly recommend all users to update to this release.
- Improved contrast and exposure under low light conditions, IR and WDR conditions

## **Version 3.16.0.110 – Released May 19, 2017**

- Added support for Tamper Detection
- Corrected an issue where formatting SD cards via the WebUI would not actually initiate the process.
- Corrected an issue where privacy zones could not be created at the lower half of the view.

## **Version 3.12.0.34 – Released Oct 1, 2016**

- Improved image in low light scenes

## **Version 3.12.0.26 – Released Sep 22, 2016**

- Initial firmware release for the following H4 SL cameras:
  - 1.3C-H4SL-DO1-IR
  - 2.0C-H4SL-DO1-IR
  - 1.3C-H4SL-BO1-IR
  - 2.0C-H4SL-BO1-IR